



## ALTERNATORS



Used on: Land Rover 88, 109 2.25 Diesel & 90, 110 2.5 Diesel & 109 2.6

Replaces:

0986031661	0986044581	0986044641	110178
23983	24024	24026	24082
24099	43356118	436140	436142
436144	8EL725620-001	8EL725628-001	9124476002
ADU1991	ADU5440	ADU5444	CA17H
CA18H	DRA1691	DRA3015	DRA3554
GEU205	GEU207	GEU2211	GXE8211
IA0067	IA0068	LRA00100	LRA00226
LRA00356	MAR399	PRC2667	PRC4285



**LEA0001**  
14V / 45A



Used on: Land Rover 88 & 109 2.25 Diesel

Replaces:

113378	23697	23739	23740
23807	23830	23845	23846
23993	54021527	61920286	8EL725691-001
CA290IR	DRA3435	GEU2212	LRA109




**LEA0012**  
14V / 45A



Used on: Defender 90, 110, 130 V8 & Discovery V8i 3.5 & Range Rover 3.5 Efi

Replaces:

110813	24220	54022197	54022340
63324220	DRA3588	LRB00127	MAN118
MAN182	MAR118	NAB405	PRC6364




**LEA0037**  
14V / 65A



Used on: Land Rover 90, 110 V8 & Defender 90, 110 V8

Replaces:

111366	24198	436166	54022145
54022166	54022196B	54022207	54022228
54022246	54022265	54022274	54022401
54022457	8EL725913-001	9124476325	ADU8810
ASU1238	CA629IR	DRA3293	GXE2353
LRA00653	MAR106	NAB100	PRC6367



**LEA0043**  
14V / 45A



Used on: Land Rover 90, 110 2.5 TD & Defender 90 2.5 TDI (200), 110 2.5, 110 2.5 TDI (300)

Replaces:

1676689M92	24199	24318	2871A165
3538541M1	3698016M91	3698017M91	436145
436167	54022146	54022621	714/11400R
836640127	9124476321	92293C1	ADU9052
ADU9670	GEU2276	K311696	LRA00602
MAR107	MAR161	NAB101	PRC6366



**LEA0044**  
14V / 45A




All non - Lucas Elektrik A.Ş. numbers and names are for reference only.

For further inquiries; e-mail: [marketing@lucaselektrik.com](mailto:marketing@lucaselektrik.com) Fax: +90 264 276 8771

[www.lucaselektrik.com](http://www.lucaselektrik.com)



## ALTERNATORS



**LEA0056**  
14V / 65A



Used on: Defender 90, 110 2.5D & Discovery TDI (200, 300) & Range Rover 2.4 TD, 2.5 TD

Replaces:

24221	24403	54022198	54022275
54022312	54022339	54022474	54022570
54022611	54022650	AMR3412	AMR3512
AMR4249	LRB00128	MAN119	NAB406
PRC6365	PRC6383	PRC7036	RTC5681
YLE10105			



**LEA0275**  
14V / 70A



Used on: Land Rover Various Applications

Replaces:

110968	61920352	8EL737664-001	CA14591R
NAB300			



**LEA0276**  
14V / 70A  
LEA0065 With Fan&Pulley



Used on: Land Rover Various Applications

Replaces:

1005348	11.201.576	110969	147731
5011974	5022265	5023528	5023529
6159272	61920353	84AB10300AB	84AB10300MA
84AB10300MB	84AB10346MB	84FB10300AAA	8EL737665-001
943356636	AAK4521	CA14601R	IA0576
LRA00469	LRA00967	NAB301	



**LEA0453**  
14V / 120A



Used on: Discovery II 3.9 V8

Replaces:

20130198	2542591	2542838	437425
439468	DRA0093	SG12B063	SG12B082
YLE000090	YLE500090		




**LEA0454**  
14V / 150A



Used on: Discovery II 4.0 V8 & Range Rover III 3.0 TD

Replaces:

2542686	2542826	437421	439463
A14V153	SG15S030	YLE000051	YLE500180




All non - Lucas Elektrik A.Ş. numbers and names are for reference only.

For further inquiries; e-mail: [marketing@lucaselektrik.com](mailto:marketing@lucaselektrik.com) Fax: +90 264 276 8771

[www.lucaselektrik.com](http://www.lucaselektrik.com)



## ALTERNATORS



**LEA0455**  
14V / 150A



Used on: Freelander 2.0 TD4

Replaces:

0986045251	12312249966	12317787346	12317788222
12317788247	2249966	2542343	2542602
2542605	2542852	437309	437417
439305	7788222	8EL738130-001	A14V134
A14V146	A14VI47	CA17561R	DRA3808
LRA01970	TG15C038	YLE000070	YLE500170




**LEA0533**  
14V / 80A  
80A vers.of LEA0275




Used on: Land Rover Various Applications

Replaces:

110968	61920352	8EL737664-001	CA14591R
NAB300			




**LEA0559**  
14V / 105A



Used on: Freelander 1.8 16V

Replaces:

20130196	DRA3799	DRA3799N	102211-1450
102211-1451	JA17231R	LRB00417	LRB00468
YLE102060	YLE102280	YLE102370	YLE102370L




**LEA0578**  
14V / 45A



Used on: Land Rover 90, 110 V8 & Defender 90, 110 V8

Replaces:

111366	24198	436166	54022145
54022166	54022196B	54022207	54022228
54022246	54022265	54022274	54022401
54022457	8EL725913-001	9124476325	ADU8810
ASU1238	CA6291R	DRA3293	GXE2353
LRA653	MAR106	NAB100	PRC6367



**LEA0638**  
14V / 115A



Used on: Discovery 2.5 TDI & Defender Station Wagon 3.5 4x4 & Range Rover II 2.5 D, 2.5 TD

Replaces:

0986080820	111283	112021	11203205
63321321	63341321	63341358	8EL737211-001
8EL737520-001	AAK5396	AMR4248	AMR5425
CA11911R	CA13371R	DAN008	DRA3587
DRA3679	IA1134	LRB00207	LRB00384
MAN674	YLE10075	YLE10113	YLE10113E
YLE1013			

All non - Lucas Elektrik A.Ş. numbers and names are for reference only.

For further inquiries; e-mail: [marketing@lucaselektrik.com](mailto:marketing@lucaselektrik.com) Fax: +90 264 276 8771


[www.lucaselektrik.com](http://www.lucaselektrik.com)



## ALTERNATORS



**LEA0700**  
14V / 150A




Used on: Discovery III 2.7 & Range Rover Sport 2.7

Replaces:  
104210-3710 104210-3711 114704 8EL738212-901  
CA1958IR DAN987 DRA0342 LRA03028  
YLE500200 YLE500400




**LEA0701**  
14V / 150A



Used on: Land Rover LR3 V6 4000 CC

Replaces:  
104210-3700 104210-3701 6337754010 DAN986  
LRA03112 MAN7554 YLE500240 YLE500410



**LEA0755**  
14V / 150A  
With ORC Pulley



Used on: Freelander 2.2TD 4X4

Replaces:  
0121615021 0121615121 0986081400 1435647  
1455494 6G9N10300ADA 6G9N10300ADB DRA0059  
LR002899 LRA02973



**LEA0767**  
14V / 150A  
With ORC Pulley



Used on: Defender 2.4 TD4

Replaces:  
0121615002 0986047910 113958 1404791  
1572736 1581843 1712779 1747021  
5705EA 6C1T10300BA 6C1T10300BB 6C1T10300BC  
6C1T10300BD 8EL012426-491 8EL738212-131 944390479100  
965814468 9658144680 965991808 9659918080  
967614358 AC1T10300BA AC1T10300BB DRB7910  
LRA02977 MQA003 MRA47910 YLE500310


All non - Lucas Elektrik A.Ş. numbers and names are for reference only.

For further inquiries; e-mail: [marketing@lucaselektrik.com](mailto:marketing@lucaselektrik.com) Fax: +90 264 276 8771

[www.lucaselektrik.com](http://www.lucaselektrik.com)



## STARTER MOTORS



**LES0005**  
12V / 2.1kW  
10 Teeth



Used on: Land Rover 109 2.25 Diesel & 110 2.25 Diesel

Replaces:

110440	26259	26321	27446
27468	432574	8EA737246-001	9000331412
9004475056	CS997	GEU420	GEU430
GEU4430	GEU4435	GXE4435	LRS139
NSB511			




**LES0033**  
12V / 2.1kW  
9 Teeth



Used on: Land Rover 90, 110 2.5 D & Defender 90, 110 2.5 D

Replaces:

0986016910	110441	26256	27425
27460	432574	436052	8EA726214-001
9004475107	CS590	DRS3593	LRS00574
NSB512	PRC3032	RTC5249	




**LES0068**  
12V / 1.7kW  
9 Teeth



Used on: Defender 3.9 V8 & Discovery 13.5, 13.9 V8, 11 3.9 V8, 11 4.0 V8 & Range Rover 13.9, 13.9 Vogue SEI, 14.3 Vogue LSE, 13.9, 11 3.9, 11 4.6

Replaces:

0001108137	0001109040	0001110090	0001110120
0986017440	111865	458253	458566
63226801	8EA726213-001	8EA737314-001	CS1049
CS589	DRS3198	DRS3719	ERR6087
ESR2191	LRT00169	MSN139	NAD100380
NAD101190	NAD101490		




**LES0153**  
24V / 3.5kW  
10 Teeth



Used on: Land Rover 110 Military & 2.5 Diesel 24V

Replaces:

26387	27429	27461	60925076
60925100	LRS01973	NSB516	PRC4426
PRC8065			



**LES0273**  
12V / 2.2kW  
9 Teeth



Used on: Defender & Discovery II 2.5 TD

Replaces:

0986022760	113662	20510171	228000-7220
8EA737911-001	CS1242	DRS3718	LRT00171
NAD101240			


All non - Lucas Elektrik A.Ş. numbers and names are for reference only.

For further inquiries; e-mail: [marketing@lucaselektrik.com](mailto:marketing@lucaselektrik.com) Fax: +90 264 276 8771

[www.lucaselektrik.com](http://www.lucaselektrik.com)



## STARTER MOTORS




**LES0274**  
12V / 2.0kW  
9 Teeth



Used on: Freelander 2.0 TD 4X4

Replaces:

0986022621	228000-7801	8EA73823-001	DRS3805
JS1321	LRS01551	NAD101500	



**LES0309**  
12V / 2.0kW  
12 Teeth



Used on: Defender 2.2 TD4, 2.4 T4

Replaces:

0001109205	0001109324	0001109325	0001109387
0001109388	0001109391	063521093240	0986021810
5802AS	6C1T11000AB	6C1T11000AC	6C1T11000AD
6C1T11000AF	860821	8EA738258-841	943280218100
95681447	9658144780	CS1421	DRT1810
LR025840	LRS02243	MSN2144	MSR21810



**LES0348**  
12V / 2.2kW  
9 Teeth



Used on: Defender 2.5 90, 110 TDI & Discovery 2.5D & Range Rover 2.5TD

Replaces:

0001218152	0001218168	0051511501	11.139.444
112439	8EA011610-101	8EA726176-001	8EA737859-001
AZE4143	BF5T11001AA	CS1201	DRS3084
ERR5009	IS9437	LRS00728	NAD10039



**LES0410**  
12V / 1.4kW  
9 Teeth



Used on: Land Rover 2.3, 2.5 & Defender 2.5

Replaces:

0001108131	26800	26800E	26800F
26800M	63226800	DRS3416	LRS00158
MSN138	MSR138	NAD100400	PRC6613N

All non - Lucas Elektrik A.Ş. numbers and names are for reference only.

For further inquiries; e-mail: [marketing@lucaselektrik.com](mailto:marketing@lucaselektrik.com) Fax: +90 264 276 8771

[www.lucaselektrik.com](http://www.lucaselektrik.com)